

In Development

Firmware Version: 0.26

Feature	Products Affected	Workaround
USB MIDI not implemented	All Super 6	Use MIDI over DIN connectors
CC transmit limited to: Modulation Lever, Sustain Pedal, Foot Controller	All Super 6	
NRPN transmit/receive not activated	All Super 6	
MPE mode not activated	All Super 6	
MIDI patch dump not activated	All Super 6	Save program and use MIDI Program Change & MIDI Bank Select Messages