

In Development

Firmware Version: 0.23

Feature	Products Affected	Workaround	Estimated Implementation
USB MIDI not implemented	All Super 6	Use MIDI over DIN connectors	1 st Quarter 2021
CC transmit limited to: Modulation Lever, Sustain Pedal, Foot Controller	All Super 6		4 th Quarter 2020
NRPN transmit/receive not activated	All Super 6		4 th Quarter 2020
MPE mode not activated	All Super 6		1 st Quarter 2021
MIDI patch dump not activated	All Super 6	Save program and use MIDI Program Change & MIDI Bank Select Messages	1 st Quarter 2021